
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3		
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/03/2008	
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04	
Manhole ID: S19K031MH	Test ID: 1029-596	Notifications Made:X Residents, Fire, 311	

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Page 2 of 3						
,	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO				Date: 09/03/2008					
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_					_		-	isor: E.R. Crew: 04	
Ма	inhole ID: S19K031MH	Test ID: 1029-596					Notifications Made:X_ Residents, Fire, 311				
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect			urce					nage			
No.	Address		уре	Locat	ion	Sector		ea	Severity		Photo Number
1	S19I021MH	•	18	14	ļ.	01	2	25	03		1029-596_OB01-01.jpg
							ļ				
							-				
			OB	SERV	/AT	ION CO	DES				
	Source Type			Locat				S	Sector		Severity
	ain Sewer 10 MH Frame					Non-Pa			Public		No Smoke
	ervice Line 11 Storm Drain	02 Asp				Field/W	oods	02	Private		Trace
	eanout 12 Catch Basin	03 Pav									Moderate
	ownspout 13 Storm MH	04 Dri				Golf Co	urse			04	Major
	ea Drain 14 Storm Ditch	05 Sid		K	14	Other		-			
	vy. Drain 15 Excavation	06 Cu		ront							
	air. Drain 16 Water Line ound. Drai 17 Tele. Pole	07 Yaı 08 Yaı									
	dg. Interio 18 Other	08 Yai									
טט טונ	-9. 1110110 TO OHIO	u oo i ai	<u> </u>						1		

PAGE 3 of 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 596	Date: 09/03/2008	Basin: LL - 44	Manhole ID: S19K031MH
Defect No: OB01 Supervisor	:: E.R. Crew: 04		Dye Test Recommended: N
Location: S19K045MH			
Source Type: 18 Other	Sector: 0	1 Public	
Location: 14 Other	Severity: 0	3 Moderate	Drainage Area: 25
Comments: MANHOLE S19K	045MH HAS STORM DF	RAIN LID.	

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-596_OB01-01.jpg